



Tesla, Inc.
Service Bulletin

Replace Steering Column Control Module (SCCM)

SB-24-32-002
April 8, 2024

Classification		Section/Group	Mobile Service	Configuration
Campaign Bulletin		32 - Steering	Can Perform (where permitted)	All
Model Year	Model	Country/Region	Build Location	
2023	Cybertruck	United States	Giga Austin	

The model(s) and model year(s) listed are a general approximation of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.


Campaign Bulletin: This campaign bulletin addresses a non-safety-related condition and provides recommended technical diagnosis and repair procedures. Apply this procedure to the applicable vehicles.

Condition

On certain Cybertruck vehicles, the Steering Column Control Module (SCCM) does not meet Tesla quality standards.

Correction

Replace the SCCM.

 **NOTE:** If this bulletin appears as applicable to the vehicle, perform the correction without any need for inspection.

Correction Description	Correction	Time
Replace Steering Column Control Module	S012432002	0.24

Part Number	Description	Quantity
Parts Required 1813040-00-E	STEERING COLUMN CONTROL MODULE	1

This part number was current at the time of publication. Use the revision listed or later, unless otherwise specified in the [Parts Catalog](#).

Procedure

Replace the SCCM (refer to Service Manual procedure [3205111062](#)).