TESLA	Tesla, Ir Service Bull		Replace Pyrotechnic HV Battery Discor		ery Disconnect	
SB-25-16-003						
June 3, 2025						
Classification			Section/Group	Mobile Service	Configuration	
Campaign Bulletin			16 - HV Battery	Cannot Perform	All	
Model	Model Ye	ar	Country/Region	Build Location		
Model S	2012–2020		All	Fremont		
Model X	2015–2020					
	and model year(s) listed a		I al approximation of the affected VIN list	. Refer to the VIN/Bulletin Tracker or Cus	stomer/Vehicle profile to determine	

Campaign Bulletin: This campaign bulletin addresses a non-safety-related condition and provides recommended technical diagnosis and repair procedures. Apply this procedure to the applicable vehicles.

Condition

On certain Model S and Model X vehicles, the battery powered Pyrotechnic High Voltage (HV) Battery Disconnect will reach the end of its battery lifespan in the near future, which will trigger alerts and may limit the vehicle's performance.

Correction

Replace the battery powered Pyrotechnic HV Battery Disconnect with a self-powered Pyrotechnic HV Battery Disconnect.

NOTE: If this bulletin is applicable to the vehicle, perform the correction without any need for inspection.

Correction Description	Correction	Time	
		Model S	Model X
Replace Pyrotechnic HV Battery Disconnect - HV Battery 1.0 And 1.5	S012516003	2.10	N.A.
Replace Pyrotechnic HV Battery Disconnect - HV Battery 2.0	S022516003	0.54	0.66
Pyrotechnic HV Battery Disconnect Already Replaced	S032516003	0.00	0.00

	Part Number	Description	Quantity			
Parts Required	1111313-00-F 1111445-00-F	One of the following, based on the VIN: DISCONNECT,PYROTECHNIC,CUR POWERED,2000A DISCONNECT,PYROTECHNIC,CUR POWERED,2366A	1 1			
		bers were current at the time of publication. Use the revisions listed or later, e specified in the Parts Catalog.				
Special Tools	1059330-00-A 1057606-00-A 1076927-00-A	SOCKET,DR 5LOBE,E-TORX MAG,0.25INCH 1/4" DRIVE 13MM SOCKET - CEMENTEX HIOKI MODEL 3548 RESISTANCE METER				
	1055662-00-A	One of the following, based on the region: ANTI-STATIC MAT/W WRIST GROUNDING CORD AND WRI - NORTH AMERICA	IST STRAP			
	1056154-01-B	ANTI-STATIC MAT/W WRIST GROUNDING CORD AND WRI - EU SCHUKO	IST STRAP			
	1056154-02-B	ANTI-STATIC MAT/W WRIST GROUNDING CORD AND WRI - UK, IRELAND	IST STRAP			
	1056154-03-B	ANTI-STATIC MAT/W WRIST GROUNDING CORD AND WRI - SWITZERLAND	IST STRAP			
	1056154-04-B	ANTI-STATIC MAT/W WRIST GROUNDING CORD AND WRI - DENMARK	IST STRAP			
	1006653-00-A 1076921-00-A	For HV Battery 1.0/1.5 only: FLAG,REMOVED FUSE,HVBAT,MDLS FLUKE 1587 MULTI-METER				

Procedure

Replace the Pyrotechnic HV Battery Disconnect. Refer to one of the following:

- HV Battery 1.0/1.5: Service Manual procedure 16308702; Model S.
- HV Battery 2.0:

Service Manual procedure 1638502; Model S, Model X.