Tesla, Inc. Service Bulletin		*Update Vehicle Software to Enable Blinded Camera Detection*		
SB-24-00-015 September 6, 2024				
Classification		**Section/Group**	**Mobile Service**	**Configuration**
Recall Bulletin		00 - Inspection & Service	Can Perform (where permitted)	Autopilot Hardware 4
Model	**Model Year**	**Country/Region**	**Build Location**	
Model 3	2024	Asia Pacific, Europe, Middle East	Fremont, Giga Berlin, Giga Shanghai	
Model Y	2024			
Model S	2024			
Model X	2024			
The model(s) and model year(s) listed are a general approximation of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.				

Recall Bulletin: Recall Bulletins are mandatory service procedures that, unless they can be completed via a software update that a customer installs through the normal course of ownership, must be carried out by Tesla-certified Service Centers. Recall work performed by uncertified technicians could lead to unsafe conditions or voided warranty provisions.

Condition

On affected vehicles, the vehicle software may need to be updated to ensure detection of a blinded B-pillar camera as is required by UNECE R79.03. This concern may arise when certain Autosteer functions are in operation.

Correction

Inspect the vehicle software version and if necessary, update the vehicle software to version 2024.26.7 or a later version.

Correction Description	Correction	Time
Inspect Vehicle Software Version; No Software Update Needed For Blinded Camera Detection	S012400015	0.06
Inspect And Update Vehicle Software To Enable Blinded Camera Detection	S022400015	0.06

Procedure

On the vehicle touchscreen, touch **Controls** (vehicle icon) > **Software**, and then scroll down to display the vehicle software version.

- If the vehicle is operating with software version 2024.26.100 (factory version) or 2024.26.7, or a later version, no further action is necessary. Use correction code S012400015.
- If the vehicle is operating with a software version earlier than 2024.26.100 (factory version) or 2024.26.7, update the software to version 2024.6.7 or a later version (refer to Service Manual procedure 00020003; hyperlinks listed below). Use correction code S022400015.
    - 2021+ Model S Service Manual
    - 2021+ Model X Service Manual
    - 2024+ Model 3 Service Manual
    - Model Y Service Manual

For feedback on the accuracy of this document, email ServiceBulletinFeedback@tesla.com