

		Tesla, Inc. Service Bulletin		<i>Update Vehicle Software For Energy Boost Capability</i>			
SB-24-00-010 July 15, 2024							
Classification				Section/Group		Mobile Service	Configuration
Repair Bulletin				00 - Inspection & Service		Can Perform (where permitted)	Rear Wheel Drive
Model		Model Year		Country/Region		Build Location	
Model Y		2023 – 2024		United States		Fremont, Giga Texas	
The model(s) and model year(s) listed are a general approximation of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.							

Repair Bulletin: This repair bulletin provides instructions on addressing a possible customer concern regarding the operation of Tesla vehicles. These instructions should only be performed by trained professionals.

Condition

Some Model Y vehicles running a vehicle software version earlier than 2024.20.3 require a vehicle software update to be able to qualify for the Energy Boost upgrade. Vehicle operation or safety is not affected.

Correction

Inspect the vehicle software version, and if necessary, update the vehicle software to version 2024.20.3 or later.

Correction Description	Correction	Time
SB-24-00-010 Not Applicable	S012400010	0.00
Inspect Vehicle Software Version, Update Not Necessary	S022400010	0.06
Inspect And Update Vehicle Software For Energy Boost Capability	S032400010	0.06

Procedure

On the vehicle touchscreen, touch **Controls** (vehicle icon) > **Software**, and then scroll down to display the vehicle software version.

- If the vehicle is operating with software version 2024.20.3 or newer, no further action is necessary. Use correction code S022400010.
- If the vehicle is operating with a software version earlier than 2024.20.3, update the software to version 2024.20.3 or newer (refer to Service Manual procedure [00020003](#)). Use correction code S032400010.

 **NOTE:** Once the vehicle software has been updated to 2024.20.3 or later, inform the customer:

- Energy Boost can be purchased via Tesla mobile app (**Upgrades > Software Updates**), or via vehicle touchscreen (**Controls** (vehicle icon) > **Upgrades**).
- After Energy Boost is purchased, the upgrade will take effect a few hours after the vehicle is connected to Wi-Fi and set to **Park**.